

()

**INTERSTATE COUNCIL FOR STANDARDIZATION, METROLOGY AND CERTIFICATION
(ISC)**

520
2011

**(ISO 492:2002, NEQ
ISO 199:2005, NEQ)**



2012

,
» 1.0—92 «
1.2—2009 «

1 , « » (« »)
»,

4

2

3 , (« »)
12 2011 . 39—2011)

(3166) 004—97	(3166) 004—97	
	AZ AM BY KG MD RU TJ UZ	

4

:
492:2002 « » (ISO 492:2002 «Rolling
bearings — Radial bearings — Tolerances»);
199:2005 « » (ISO 199:2005 «Rolling
bearings — Thrust bearings — Tolerances»).

— (NEQ)

5

520—2002 « »

6

2011 . 232-

520—2011
1 2012 .

19

« » ,

« » .

« » ,

1	1
2	1
3	3
4	6
5	9
6	9
6.1	9
6.2	- ,	10
6.3	21
6.4	29
6.5	30
6.6	-	33
7	38
8	41
9	42
10	58
11	,	60
12	61
13	61
	()	62
	()	64
	65

Rolling bearing. General specifications

— 2012—07—01

1

3478,	4252,	4657,	5377,	5721,	6364,	831,	832,
7872,	8328,	8338,	8419,	8545,	8882,	7242,	7634,
9942,	18572,	20531,	23179,	23526,	24696,	8995,	9592,
27365,	28428.					24850,	27057,

(

),

,

,

,

-

(

)

3478.

2

8.050—73

515—77
831—75

832—78

2789—73
2893—82

2991—85 500

3189—89
3325—853395—89
3478—79
3722—81
4252—75

4657—82
5377—79
5721—75
6364—78
6870—81
7242—81
7634—75
7872—89
8328—75
8338—75
8419—75
8530—90 (2982—72, 2983—75)
8545—75
8882—75
8995—75
9142—90
9592—75
9942—90
10354—82
13014—80
14192—96
16148—79
16272—79
18242—72
18321—73
18572—81
18854—94 (76—87)
18855—94 (281—89)
()
20531—75
22696—77
23179—78
23526—79
24208—80
24297—87
24634—81

24696—81

24810—81
24850—81

24955—81
25255—82
25256—82
25455—82
25548—82

27057—86
27365—87

28428—90

1

3

24955, 25256 25548,

3.1 (self-aligning rolling bearing):

3.2 (external-aligning rolling bearing):

3.3 (open rolling bearing):

3.4 (capped rolling bearing):

3.5 (instrument precision rolling bearing):

3.6 (paired mounting):

3.7 (stack mounting):

3.8 (matched rolling)

3.9 (subunit):

3.11 (basic type):

3189

1 205.

2 42726

3.12 (modification of basic type):

1 72-205

2 42726 4

3.13 (separable bearing ring):

3.14 (interchangeable bearing ring):

3.15 (nominal outer ring flange width):

3.16 C_{1s} (single outer ring flange width):

3.17 (nominal effective width of inner subunit):

3.18 T_{1s} (actual effective width of inner subunit):

3.19 T_2 (nominal effective width of outer ring):

3.20 T_{2s} (actual effective width of outer ring):

()

3.21 r_s (single chamfer dimension):

3.22

(parallelism of ring raceway with respect to the face):

3.23

having a flange with respect to the back face of the flange):

 s_{e1} (parallelism of outer ring raceway**3.24**

(perpendicularity of ring face with respect to the bore):

3.25

side surface with respect to the face):

 S_D (perpendicularity of outer ring out-

1,2

3.26

larity of outer ring outside surface with respect to the flange back face):

 S_{D1} (perpendicu-**3.27**

washer raceway and back face):

 S_j (variation in thickness between shaft1,2
1,2**3.28**

housing washer raceway and back face):

 S_e (variation in thickness between**3.29**

inner ring of assembled bearing):

 K_{ja} (radial runout of**3.30**

ring of assembled bearing):

(radial runout of outer

3.31

flange back face of assembled bearing):

 S_{ea1} (axial runout of outer ring

3.32 (gamma-percentile life):

[27.002—89, 6.15]

3.33 (measuring force):

3.34 (measuring load):


4

4.1

- — ;
- — ;
- i — ;
- m — ;
- — , ;
- — ;
- s — ;
- w — ;
- 1,2 — ,

4.2

1.



4.3

—	;
B_s —	;
V_{Bs} —	;
Ag_s —	;
—	;
C_s —	;
C_{1s} —	;
V_{Cs} —	;
—	;
V_1 —	;
A_{c1s} —	;
D_m —	;
D_{mp} —	;
D_s —	;
D —	;
a_{Ds} —	;
V_Dg —	;
V_Dgp —	;
V_{Dmp} —	;
A_{Dm} —	;
A_{Dmp} —	;
a_{Di_s} —	;
d_m —	;
d_{mp} —	;
d_s —	;
d —	;
V_{ds} —	;
A_{ds} —	;
A_{dm} —	;
V_{dmp} —	;
A_{dmp} —	();
V_{dsp} —	;
A_{dim_p} —	;
—	;
—	;
K_j —	;
K_{ia} —	;
S_D —	;
S_{D1} —	;
S_d —	;

S_e —

S_{e1} —

S_{ea} —

s_{ea1} —

S_j —

S_{la} —


r_s —

$r_{s \min}$ —

$r_{s \max}$ —

4.4

2.



— () ; —
; 2 —

2 —

4.5

T_s —

7_{1s} —

T_{2s} —


$a7_s$ —

$A7_{1s}$ —

7_2 —

4.6

3.



d —
 D —

3 —

4.7

S; -

'/Dsp -

;

'/dsp -

;

v_{d2} sp

;

\backslash^{ADmp}
 dmp

;

$\backslash 2$

—

90°;

S_e —

—

90°;

A_{Ts} —
 A_{ris} —


5

3478,

6

6.1

, , , , ,
, 6, 5, 4, , 2 —
;
- 0, , 6 , 6, 5, 4, 2 —
- , 6, 5, 4, 2 —



492 [1], 620 [2], AFBMA 20 [3], JISB 1514 [4], AFBMA 19.1 [5],
 620 [2] 199 [6]

6.2**6.2.1**

6.2,

6.5.

6.4.

6.2.2

(. 1 2)

1 —

d, ° /	^cfep				^ /	S _{ia} ¹⁾ , si)	^Bs				vBs,	
	, 8, 9		1,7	2, 3, 4, 5, 6			-		-			
	0,6	0	-8	10	8	6	6	10	20	24		
0,6	2,5	»	0	-8	10	8	6	6	10	20	24	0
» 2,5	» 10	»	0	-8	10	8	6	6	10	20	24	0
» 10	» 18	»	0	-8	10	8	6	6	10	20	24	0
» 18	» 30	»	0	-10	13	10	8	8	13	20	24	0
» 30	» 50	»	0	-12	15	12	9	9	15	20	24	0
» 50	» 80	»	0	-15	19	19	11	11	20	25	30	0
» 80	» 120	»	0	-20	25	25	15	15	25	25	30	0
» 120	» 180	»	0	-25	31	31	19	19	30	30	35	0
» 180	» 250	»	0	-30	38	38	23	23	40	30	35	0
» 250	» 315	»	0	-35	44	44	26	26	50	35	42	0
» 315	» 400	»	0	-40	50	50	30	30	60	40	48	0
» 400	» 500	»	0	-45	56	56	34	34	65	45	54	0
» 500	» 630	»	0	-50	63	63	38	38	70	—	—	0
» 630	» 800	»	0	-75	—	—	—	—	80	—	—	0
» 800	» 1000	»	0	-100	—	—	—	—	90	—	—	0
» 1000	» 1200	»	0	-125	—	—	—	—	100	—	—	0
» 1200	» 1600	»	0	-160	—	—	—	—	120	—	—	0
» 1600	» 2000	»	0	-200	—	—	—	—	140	—	—	0
1) 2)												

D, .)					«	§ 2) & S 2)	^A Cs ^A C1s ³⁾	^v Cis >				
		0,8,9	1,7	2,3,4,5,6	1,2,3,4,5,6,7,8								
.			
2,5	0	-8	10	8	6	10	6	15	40				
.2,5 6 »	0	-8	10	8	6	10	6	15	40				
» 6 » 18 »	0	-8	10	8	6	10	6	15	40				
» 18 » 30 »	0	-9	12	9	7	12	7	15	40				
» 30 » 50 »	0	-11	14	11	8	16	8	20	40				
» 50 » 80 »	0	-13	16	13	10	20	10	25	40				
» 80 » 120 »	0	-15	19	19	11	26	11	35	45				
» 120 » 150 »	0	-18	23	23	14	30	14	40	50				
» 150 » 180 »	0	-25	31	31	19	38	19	45	60				
» 180 » 250 »	0	-30	38	38	23	—	23	50	70				
» 250 » 315 »	0	-35	44	44	26	—	26	60	80				
» 315 » 400 »	0	-40	50	50	30	—	30	70	90				
» 400 » 500 »	0	-45	56	56	34	—	34	80	100				
» 500 » 630 »	0	-50	63	63	38	—	38	100	120				
» 630 » 800 »	0	-75	94	94	55	—	55	120	140				
» 800 » 1000 »	0	-100	125	125	75	—	75	140	160				
» 1000 » 1250 »	0	-125	—	—	—	—	—	160	—				
» 1250 » 1600 »	0	-160	—	—	—	—	—	190	—				
» 1600 » 2000 »	0	-200	—	—	—	—	—	220	—				
» 2000 » 2500 »	0	-250	—	—	—	—	—	250	—				
^ 2) 3)													
Dj		33.											

6.2.3

6(. 3 4)

520—20-1-1

3-

6

ff, .	*4 .	% 0,8,9 1,7 2,3,4,5,6			A		Sd	5, 5,*	ABs			2) .	
			
			
0,6	0	-7	9	7	5	5	5	10	12	0	-40	-	12
.0,6 2,5 »	0	-7	9	7	5	5	5	10	12	0	-40	-	12
» 2,5 » 10 »	0	-7	9	7	5	5	6	10	12	0	-120	-250	15
» 10 » 18 »	0	-7	9	7	5	5	7	10	12	0	-120	-250	20
» 18 » 30 »	0	-8	10	8	6	6	8	10	12	0	-120	-250	20
» 30 » 50 »	0	-10	13	10	8	8	10	10	12	0	-120	-250	20
» 50 » 80 »	0	-12	15	15	9	9	10	12	15	0	-150	-380	25
» 80 » 120 »	0	-15	19	19	11	11	13	12	15	0	-200	-380	25
» 120 » 180 »	0	-18	23	23	14	14	18	15	18	0	-250	-500	30
» 180 » 250 »	0	-22	28	28	17	17	20	15	18	0	-300	-500	30
» 250 » 315 »	0	-25	31	31	19	19	25	17	21	0	-350	-500	35
» 315 » 400 »	0	-30	38	38	23	23	30	20	24	0	-400	-630	40
» 400 » 500 »	0	-35	44	44	26	26	35	22	27	0	-450	-	45
» 500 » 630 »	0	-40	50	50	30	30	40	25	-	0	-500	-	50

A

2)

D,								^A Dmp)	“	^A Cs' ³⁾ AC1s	^A L _{Cs¹} 1/3)				
		0,8,9	1,7	2,3,4,5,6	1,2,3,4,5,6,7,8										
.				
2,5	0	-7	9	7	5	9	5	8	20						
.2,5 « 6 »	0	-7	9	7	5	9	5	8	20						
» 6 » 18 »	0	-7	9	7	5	9	5	8	20						
» 18 » 30 »	0	-8	10	8	6	10	6	9	20						
» 30 » 50 »	0	-9	11	9	7	13	7	10	20						
» 50 » 80 »	0	-11	14	11	8	16	8	13	20						
» 80 » 120 »	0	-13	16	16	10	20	10	18	22						
» 120 » 150 »	0	-15	19	19	11	25	11	20	25						
» 150 » 180 »	0	-18	23	23	14	30	14	23	30	^A B _s	¹ / _{B_s}				
» 180 » 250 »	0	-20	25	25	15	—	15	25	35						
» 250 » 315 »	0	-25	31	31	19	—	19	30	40						
» 315 » 400 »	0	-28	35	35	21	—	21	35	45						
» 400 » 500 »	0	-33	41	41	25	—	25	40	50						
» 500 » 630 »	0	-38	48	48	29	—	29	50	60						
» 630 » 800 »	0	-45	56	56	34	—	34	60	70						
» 800 » 1000	0	-60	75	75	45	—	45	75	80						
^A															
²⁾															
³⁾															

6.2.4

5(. 5 6)

5-

5

520—20-1-1

d, d,			Δdsp		%	,	Si	ΔBs			2)				
			0,8,9	1,2,3,4,5,6,7											
0,6	.	0	-5	5	4	3	4	7	7	0	-40	-250	5		
.6 2,5 »	»	0	-5	5	4	3	4	7	7	0	-40	-250	5		
» 2,5 » 10 »	»	0	-5	5	4	3	4	7	7	0	-40	-250	5		
» 10 » 18 »	»	0	-5	5	4	3	4	7	7	0	-80	-250	5		
» 18 30 »	»	0	-6	6	5	3	4	8	8	0	-120	-250	5		
» 30 » 50 »	»	0	-8	8	6	4	5	8	8	0	-120	-250	5		
» 50 » 80 »	»	0	-9	9	7	5	5	8	8	0	-150	-250	6		
» 80 » 120 »	»	0	-10	10	8	5	6	9	9	0	-200	-380	7		
» 120 » 180 »	»	0	-13	13	10	7	8	10	10	0	-250	-380	8		
» 180 » 250 »	»	0	-15	15	12	8	10	11	13	0	-300	-500	10		
» 250 » 315 »	»	0	-18	18	14	9	13	13	15	0	-350	-500	13		
» 315 » 400 »	»	0	-23	23	18	12	15	15	20	0	-400	-630	15		

^

2)

D ₁			% 0,8,9 1,2,3,4,5,6,7		ΔDmp	«	1) 2)	§ U,2)	9 ₁ 2)	ACs ^{1A} C1s ^{2J})					
2,5	.	0	-5	5	4	3	5	8	8	11	5				
2,5 « 6	»	0	-5	5	4	3	5	8	8	11	5				
» 6 » 18	»	0	-5	5	4	3	5	8	8	11	5				
» 18 » 30	»	0	-6	6	5	3	6	8	8	11	5				
» 30 » 50	»	0	-7	7	5	4	7	8	8	11	5				
» 50 » 80	»	0	-9	9	7	5	8	8	10	14	6				
» 80 » 120	»	0	-10	10	8	5	10	9	11	16	8				
» 120 » 150	»	0	-11	11	8	6	11	10	13	18	8				
» 150 » 180	»	0	-13	13	10	7	13	10	14	20	8				
» 180 » 250	»	0	-15	15	11	8	15	11	15	21	10				
» 250 » 315	»	0	-18	18	14	9	18	13	18	25	11				
» 315 » 400	»	0	-20	20	15	10	20	13	20	28	13				
» 400 » 500	»	0	-23	23	17	12	23	15	23	33	15				
» 500 » 630	»	0	-28	28	21	14	25	18	25	35	18				
» 630 » 800	»	0	-35	35	26	18	30	20	30	42	20				

Λ
2)D₁

33.

6.2.5

$$4 \begin{pmatrix} . & & 1 & 8 \end{pmatrix}$$

7 -

4

ff,	Admp	%		%	Sd	S_d^2	ABs					2)
		0,8,9	1,2,3,4,5,6,7									
		.	.									
0,6	0	-4	4	3	2	2,5	3	3	0	-40	-250	2,5
0,6 2,5 »	0	-4	4	3	2	2,5	3	3	0	-40	-250	2,5
» 2,5 » 10 »	0	-4	4	3	2	2,5	3	3	0	-40	-250	2,5
» 10 » 18 »	0	-4	4	3	2	2,5	3	3	0	-80	-250	2,5
» 18 » 30 »	0	-5	5	4	2,5	3	4	4	0	-120	-250	2,5
» 30 » 50 »	0	-6	6	5	3	4	4	4	0	-120	-250	3
» 50 » 80 »	0	-7	7	5	3,5	4	5	5	0	-150	-250	4
» 80 » 120 »	0	-8	8	6	4	5	5	5	0	-200	-380	4
» 120 » 180 »	0	-10	10	8	5	6	6	7	0	-250	-380	5
» 180 » 250 »	0	-12	12	9	6	8	7	8	0	-300	-500	6

D _i	^A D _{mp} , 11			^A D _{mp}	«	2) 9,3) V	§ 2),3)	9 1)									
								
		2,5	.	0	4	4	3	2	3	4	5	2,5					
.	2,5	6	»	0	4	4	3	2	3	4	5	2,5					
»	6	»	18	»	-4	4	3	2	3	4	5	2,5					
»	18	»	30	»	-5	5	4	2,5	4	4	5	2,5					
»	30	»	50	»	-6	6	5	3	5	4	5	2,5					
»	50	»	80	»	-1	1	5	3,5	5	4	5	A _{BS} 3					
»	80	»	120	»	-8	8	6	4	6	5	6	4					
»	120	»	150	»	-9	9	7	5	7	5	7	5					
»	150	»	180	»	-10	10	8	5	8	5	8	5					
»	180	»	250	»	-11	11	8	6	10	7	10	7					
»	250	»	315	»	-13	13	10	7	11	8	10	7					
»	315	»	400	»	-15	15	11	8	13	10	13	8					

^

1,2,3,4,5,6 7.

2)

3)

Dj

33.

8 6.2.6

(. 9 10)

9-

520—20-1-1

ff,	^A Dmp		^A dsp	^A	, , ,	*		3s		
	
0,6 .	0	4	4	2,5	2	2	2	0	-40	2
0,6 2,5 »	0	4	4	2,5	2	2	2	0	-40	2
» 2,5 » 10 »	0	-4	4	2,5	2	2	2	0	-40	2
» 10 » 18 »	0	-4	4	2,5	2	2	2	0	-80	2
» 18 » 30 »	0	-4	4	2,5	2,5	2	2,5	0	-120	2
» 30 » 50 »	0	-4	4	2,5	2,5	2	2,5	0	-120	2
» 50 » 80 »	0	-5	5	2,5	2,5	2	2,5	0	-125	2
» 80 » 120 »	0	-5	5	2,5	2,5	2,5	2,5	0	-125	2,5
» 120 » 150 »	0	-1	1	3,5	2,5	2,5	2,5	0	-125	2,5
» 150 » 180 »	0	-1	1	3,5	5	4	5	0	-125	4
» 180 » 250 »	0	-9	9	4,5	6	5	1	0	-150	5

^A 1,2,3,4,5, 1.

2) _____.

10-

L/j IVIVI	^A Dmp V ^I			^A Dmp	,	2) o 3)	^S 1, 2), 3), 2), 3)	^A Cs ^A Cls 3)		
	
2,5 .	0	-3	3	2	2	2	2			1,5
2,5 6 »	0	-3	3	2	2	2	2			1,5
» 6 » 18 »	0	-3	3	2	2	2	2			1,5
» 18 » 30 »	0	-4	4	2	2,5	2	2,5			2
» 30 » 50 »	0	-4	4	2	2,5	2	2,5			2
» 50 » 80 »	0	-4	4	2	4	2	4	^A Bs	-	2
» 80 » 120 »	0	-5	5	2,5	5	2,5	5			2,5
» 120 » 150 »	0	-5	5	2,5	5	2,5	5			2,5
» 150 » 180 »	0	-1	1	3,5	5	2,5	5			2,5
» 180 » 250 »	0	-8	8	4	1	4	1			4
» 250 » 315 »	0	-10	10	5	8	6	8			5
» 315 » 400 »	0	-12	12	6	10	1	10			6

^A 1,2,3,4,5, 1.

2) _____.

ff,	Admp	1/dsp	%	Aia	Sia ⁽²⁾	ABs			1/Bs		
0,6	0	-2,5	2,5	1,5	1,5	1,5	1,5	0	-40	-250	1,5
0,6 2,5 »	0	-2,5	2,5	1,5	1,5	1,5	1,5	0	-40	-250	1,5
» 2,5 » 10 »	0	-2,5	2,5	1,5	1,5	1,5	1,5	0	-40	-250	1,5
» 10 » 18 »	0	-2,5	2,5	1,5	1,5	1,5	1,5	0	-80	-250	1,5
» 18 » 30 »	0	-2,5	2,5	1,5	2,5	1,5	2,5	0	-120	-250	1,5
» 30 » 50 »	0	-2,5	2,5	1,5	2,5	1,5	2,5	0	-120	-250	1,5
» 50 » 80 »	0	-4	4	2	2,5	1,5	2,5	0	-150	-250	1,5
» 80 » 120 »	0	-5	5	2,5	2,5	2,5	2,5	0	-200	-380	2,5
» 120 » 150 »	0	-1	1	3,5	2,5	2,5	2,5	0	-250	-380	2,5
» 150 » 180 »	0	-1	1	3,5	5	4	5	0	-250	-380	4
» 180 » 250 »	0	-8	8	4	5	5	5	0	-300	-500	5

1,2,3,4,5, 1.

^

2)

D, .	^A Dmp		V/ ¹	^A Dmp	«	²⁾ O ³⁾	^S ²⁾ > ³⁾	⁹ ^A real ³⁾	^A Cs ³⁾ ^A C ¹ s		^A Cs ¹ ^A Cl ^{A'}
	
2,5 .	0	-2,5	2,5	1,5	1,5	1,5	1,5	3	.	.	1,5
2,5 » 6 »	0	-2,5	2,5	1,5	1,5	1,5	1,5	3	.	.	1,5
» 6 » 18 »	0	-2,5	2,5	1,5	1,5	1,5	1,5	3	.	.	1,5
» 18 » 30 »	0	4	4	2	2,5	1,5	2,5	4	.	.	1,5
» 30 » 50 »	0	4	4	2	2,5	1,5	2,5	4	.	.	1,5
» 50 » 80 »	0	4	4	2	4	1,5	4	6	1,5
» 80 » 120	0	-5	5	2,5	5	2,5	5	1	.	.	2,5
» 120 » 150 »	0	-5	5	2,5	5	2,5	5	1	.	.	2,5
» 150 » 180 »	0	-1	1	3,5	5	2,5	5	1	.	.	2,5
» 180 » 250 »	0	-8	8	4	1	4	1	10	.	.	4
» 250 » 315 »	0	-8	8	4	1	5	1	10	.	.	5
» 315 » 400 »	0	-10	10	5	8	1	8	11	.	.	1

6.3**6.3.1**

6.3,

6.5.

6.4.

6.3.2 0 (. 13—15)

13 —

0

d,	v		.	.	*ia. Ki	s _d
	.	.				
10 18 .	0	-12	12	9	15	20
. 18 » 30 »	0	-12	12	9	18	20
» 30 » 50 »	0	-12	12	9	20	20
» 50 » 80 »	0	-15	15	11	25	25
» 80 » 120 »	0	-20	20	15	30	25
» 120 » 180 »	0	-25	25	19	35	30
» 180 » 250 »	0	-30	30	23	50	30
» 250 » 315 »	0	-35	35	26	60	35
» 315 » 400 »	0	-40	40	30	70	40

14 —

0

D,			vDsp	vDmp	.
	.	.			
18 30 .	0	-12	12	9	18
. 30 » 50 »	0	-14	14	11	20
» 50 » 80 »	0	-16	16	12	25
» 80 » 120 »	0	-18	18	14	35
» 120 » 150 »	0	-20	20	15	40
» 150 » 180 »	0	-25	25	19	45
» 180 » 250 »	0	-30	30	23	50
» 250 » 315 »	0	-35	35	26	60
» 315 » 400 »	0	-40	40	30	70
» 400 » 500 »	0	-45	45	34	80
» 500 » 630 »	0	-50	50	38	100

—

D₁

33.

15 —
0

,

d,	^A Bs		^A Cs		⁷ s		^A T1s		^A T2s	

10 18 .	0	-200	0	-200	+250	-250	+125	-125	+ 125	-125
. 18 » 30 »	0	-200	0	-200	+250	-250	+125	-125	+ 125	-125
» 30 » 50 »	0	-240	0	-240	+250	-250	+125	-125	+ 125	-125
» 50 » 80 »	0	-300	0	-300	+250	-250	+125	-125	+ 125	-125
» 80 » 120 »	0	-400	0	-400	+500	-500	+250	-250	+250	-250
» 120 » 180 »	0	-500	0	-500	+750	-750	+375	-375	+375	-375
» 180 » 250 »	0	-600	0	-600	+750	-750	+375	-375	+375	-375
» 250 » 315 »	0	-700	0	-700	+750	-750	+375	-375	+375	-375
» 315 » 400 »	0	-800	0	-800	+ 1000	-1000	+500	-500	+500	-500

6.3.3

(. . 16—18)

16 —

d	/		^A cfep	.	*ia. Ki	9 1)
	.	.				
10 .	0	-12	12	9	15	20
10 » 18 »	0	-12	12	9	15	20
» 18 » 30 »	0	-12	12	9	18	20
» 30 » 50 »	0	-12	12	9	20	20
» 50 » 80 »	0	-15	15	11	25	25
» 80 » 120 »	0	-20	20	15	30	25
» 120 » 180 »	0	-25	25	19	35	30
» 180 » 250 »	0	-30	30	23	50	30
» 250 » 315 »	0	-35	35	26	60	35
» 315 » 400 »	0	-40	40	30	70	40
» 400 » 500 »	0	-45	45	34	80	—
» 500 » 630 »	0	-60	60	40	90	—
» 630 » 800 »	0	-75	75	45	100	—
» 800 » 1000 »	0	-100	100	55	115	—
» 1000 » 1250 »	0	-125	125	65	130	—
» 1250 » 1600 »	0	-160	160	80	150	—
» 1600 » 2000 »	0	-200	200	100	170	—

^

17 —

D,	^A Dmp		^V Dsp	^V Dmp	*

18 .	0	-12	12	9	18
18 » 30 »	0	-12	12	9	18
» 30 » 50 »	0	-14	14	11	20
» 50 » 80 »	0	-16	16	12	25
» 80 » 120 »	0	-18	18	14	35
» 120 » 150 »	0	-20	20	15	40
» 150 » 180 »	0	-25	25	19	45
» 180 » 250 »	0	-30	30	23	50
» 250 » 315 »	0	-35	35	26	60
» 315 » 400 »	0	-40	40	30	70
» 400 » 500 »	0	-45	45	34	80
» 500 » 630 »	0	-50	50	38	100
» 630 » 800 »	0	-75	80	55	120
» 800 » 1000 »	0	-100	100	75	140
» 1000 » 1250 »	0	-125	130	90	160
» 1250 » 1600 »	0	-160	170	100	180
» 1600 » 2000 »	0	-200	210	110	200
» 2000 » 2500 »	0	-250	265	120	220
—		D ₁	33.		

18 — — ,

d,	Bs		Cs		7s		^A T1s		^A 72s	

10 .	0	-120	0	-120	+200	0	+ 100	0	+ 100	0
10 » 18 »	0	-120	0	-120	+200	0	+ 100	0	+ 100	0
» 18 » 30 »	0	-120	0	-120	+200	0	+ 100	0	+ 100	0
» 30 » 50 »	0	-120	0	-120	+200	0	+ 100	0	+ 100	0
» 50 » 80 »	0	-150	0	-150	+200	0	+ 100	0	+ 100	0
» 80 » 120 »	0	-200	0	-200	+200	-200	+ 100	-100	+ 100	-100
» 120 » 180 »	0	-250	0	-250	+350	-250	+ 150	-150	+200	-100
» 180 » 250 »	0	-300	0	-300	+350	-250	+ 150	-150	+200	-100
» 250 » 315 »	0	-350	0	-350	+350	-250	+ 150	-150	+200	-100
» 315 » 400 »	0	-400	0	-400	+400	-400	+200	-200	+200	-200
» 400 » 500 »	0	-450	0	-450	+450	-450	+225	-225	+225	-225
» 500 » 630 »	0	-500	0	-500	+500	-500	—	—	—	—
» 630 » 800 »	0	-750	0	-750	+600	-600	—	—	—	—
» 800 » 1000 »	0	-1000	0	-1000	+750	-750	—	—	—	—
» 1000 » 1250 »	0	-1250	0	-1250	+900	-900	—	—	—	—
» 1250 » 1600 »	0	-1600	0	-1600	+1050	-1050	—	—	—	—
» 1600 » 2000 »	0	-2000	0	-2000	+1200	-1200	—	—	—	—

6.3.4

6

16 17

19.

19 —
6

d,	ABs		ACs		7s		AT1s		AT2s	
10	0	-50	0	-100	+100	0	+50	0	+50	0
10 » 18 »	0	-50	0	-100	+100	0	+50	0	+50	0
» 18 » 30 »	0	-50	0	-100	+100	0	+50	0	+50	0
» 30 » 50 »	0	-50	0	-100	+100	0	+50	0	+50	0
» 50 » 80 »	0	-50	0	-100	+100	0	+50	0	+50	0
» 80 » 120 »	0	-50	0	-100	+100	0	+50	0	+50	0
» 120 » 180 »	0	-50	0	-100	+150	0	+50	0	+100	0
» 180 » 250 »	0	-50	0	-100	+150	0	+50	0	+100	0
» 250 » 315 »	0	-50	0	-100	+200	0	+100	0	+100	0
» 315 » 400 »	0	-50	0	-100	+200	0	+100	0	+100	0
» 400 » 500 »	0	-50	0	-100	+200	0	+100	0	+100	0

6.3.5

6 (. 20—22)

20 —

6

d,	/		^*0	v _{dmp}	*ia, ,	s _d
10 18	0	-7	7	5	7	10
. 18 » 30 »	0	-8	8	6	8	10
» 30 » 50 »	0	-10	10	8	10	10
» 50 » 80 »	0	-12	12	9	10	12
» 80 » 120 »	0	-15	15	11	13	12
» 120 » 180 »	0	-18	18	14	18	15
» 180 » 250 »	0	-22	22	16	20	15
» 250 » 315 »	0	-25	—	—	25	17
» 315 » 400 »	0	-30	—	—	30	20

21 —

6

D,			v _{Dsp}	v _{Dmp}	, ,
18 30	0	-8	8	6	9
. 30 » 50 »	0	-9	9	7	10
» 50 » 80 »	0	-11	11	8	13
» 80 » 120 »	0	-13	13	10	18
» 120 » 150 »	0	-15	15	11	20
» 150 » 180 »	0	-18	18	14	23
» 180 » 250 »	0	-20	20	15	25
» 250 » 315 »	0	-25	25	19	30
» 315 » 400 »	0	-28	28	21	35
» 400 » 500 »	0	-33	—	—	40
» 500 » 630 »	0	-38	—	—	50

—

D₁

33.

22 —
6

$d,$	^ABs		^AO		^7s		$^A\text{T1s}$		$^A\text{T2s}$	

10 18 .	0	-200	0	-200	+250	-250	+ 125	-125	+ 125	-125
. 18 » 30 »	0	-200	0	-200	+250	-250	+ 125	-125	+ 125	-125
» 30 » 50 »	0	-240	0	-240	+250	-250	+ 125	-125	+ 125	-125
» 50 » 80 »	0	-300	0	-300	+250	-250	+ 125	-125	+ 125	-125
» 80 » 120 »	0	-400	0	-400	+500	-500	+250	-250	+250	-250
» 120 » 180 »	0	-500	0	-500	+750	-750	+375	-375	+375	-375
» 180 » 250 »	0	-600	0	-600	+750	-750	+375	-375	+375	-375
» 250 » 315 »	0	-700	0	-700	+750	-750	+375	-375	+375	-375
» 315 » 400 »	0	-800	0	-800	+1000	-1000	+500	-500	+500	-500

6.3.6 5 (. 23—25)

23—

5

$d,$	V		$^A\text{cfep}$	$^A /$	^Aia	s_d
	.	.				
10 .	0	-7	5	5	5	7
. 10 18 »	0	-7	5	5	5	7
» 18 » 30 »	0	-8	6	5	5	8
» 30 » 50 »	0	-10	8	5	6	8
» 50 » 80 »	0	-12	9	6	7	8
» 80 » 120 »	0	-15	11	8	8	9
» 120 » 180 »	0	-18	14	9	11	10
» 180 » 250 »	0	-22	17	11	13	11
» 250 » 315 »	0	-25	19	13	13	13
» 315 » 400 »	0	-30	23	15	15	15
» 400 » 500 »	0	-35	28	17	20	17
» 500 » 630 »	0	-40	35	20	25	20
» 630 » 800 »	0	-50	45	25	30	25
» 800 » 1000 »	0	-60	60	30	37	30
» 1000 » 1250 »	0	-75	75	37	45	40
» 1250 » 1600 »	0	-90	90	45	55	50

D,	^A Dmp		^v Dsp	^A Dmp	.	¹⁾ , ^A D1

18 .	0	-8	6	5	6	8
. 18 » 30 »	0	-8	6	5	6	8
» 30 » 50 »	0	-9	7	5	7	8
» 50 » 80 »	0	-11	8	6	8	8
» 80 » 120 »	0	-13	10	7	10	9
» 120 » 150 »	0	-15	11	8	11	10
» 150 » 180 »	0	-18	14	9	13	10
» 180 » 250 »	0	-20	15	10	15	11
» 250 » 315 »	0	-25	19	13	18	13
» 315 » 400 »	0	-28	22	14	20	13
» 400 » 500 »	0	-33	26	17	24	17
» 500 » 630 »	0	-38	30	20	30	20
» 630 » 800 »	0	-45	36	25	36	25
» 800 » 1000 »	0	-60	45	30	43	30
» 1000 » 1250 »	0	-80	65	38	52	38
» 1250 » 1600 »	0	-100	90	50	62	50
» 1600 » 2000 »	0	-125	120	65	73	65

1)

D₁

33.

d,	^A Bs		^A Cs		⁷ s		^A T1s		^A T2s	

10 .	0	-200	0	-200	+200	-200	+ 100	-100	+ 100	-100
10 » 18 »	0	-200	0	-200	+200	-200	+ 100	-100	+ 100	-100
» 18 » 30 »	0	-200	0	-200	+200	-200	+ 100	-100	+ 100	-100
» 30 » 50 »	0	-240	0	-240	+200	-200	+ 100	-100	+ 100	-100
» 50 » 80 »	0	-300	0	-300	+200	-200	+ 100	-100	+ 100	-100
» 80 » 120 »	0	-400	0	-400	+200	-200	+ 100	-100	+ 100	-100
» 120 » 180 »	0	-500	0	-500	+350	-250	+ 150	-150	+200	-100
» 180 » 250 »	0	-600	0	-600	+350	-250	+ 150	-150	+200	-100
» 250 » 315 »	0	-700	0	-700	+350	-250	+ 150	-150	+200	-100
» 315 » 400 »	0	-800	0	-800	+400	-400	+200	-200	+200	-200
» 400 » 500 »	0	-900	0	-900	+450	-450	+225	-225	+225	-225
» 500 » 630 »	0	-1100	0	-1100	+500	-500	-	-	-	-
» 630 » 800 »	0	-1600	0	-1600	+600	-600	-	-	-	-
» 800 » 1000 »	0	-2000	0	-2000	+750	-750	-	-	-	-
» 1000 » 1250 »	0	-2000	0	-2000	+750	-750	-	-	-	-
» 1250 » 1600 »	0	-2000	0	-2000	+900	-900	-	-	-	-

6.3.7

4 (. 26—28)

26 —

4

d,	Ac/mp' As		^cfep				S_d	S_ia

10	0	-5	4	4	3	3	3	3
10 18 »	0	-5	4	4	3	3	3	3
» 18 » 30 »	0	-6	5	4	3	4	4	4
» 30 » 50 »	0	-8	6	5	4	4	4	4
» 50 » 80 »	0	-9	7	5	4	5	4	4
» 80 » 120 »	0	-10	8	5	5	5	5	5
» 120 » 180 »	0	-13	10	7	6	6	7	7
» 180 » 250 »	0	-15	11	8	8	7	8	8
» 250 » 315 »	0	-18	12	9	9	8	9	9

27 —

4

D,	$\wedge D_{mp}$, $\wedge D_s$		v_{Dsp}	$\wedge D_{mp}$	*	1), $\wedge D_1$	$\$ 1)$	$\wedge 1$
	.	.						
18 .	0	-6	5	4	4	4	5	7
» 18 » 30 »	0	-6	5	4	4	4	5	7
» 30 » 50 »	0	-7	5	5	5	4	5	7
» 50 » 80 »	0	-9	7	5	5	4	5	7
» 80 » 120 »	0	-10	8	5	6	5	6	8
» 120 » 150 »	0	-11	8	6	7	5	7	10
» 150 » 180 »	0	-13	10	7	8	5	8	11
» 180 » 250 »	0	-15	11	8	10	7	10	14
» 250 » 315 »	0	-18	14	9	11	8	10	14
» 315 » 400 »	0	-20	15	10	13	10	13	18

1)

D₁

33.

28 —
4

d,	^Bs		^Cs		7s		^T1s		^72s	
10	0	-200	0	-200	+200	-200	+ 100	-100	+ 100	-100
10 18 »	0	-200	0	-200	+200	-200	+ 100	-100	+ 100	-100
» 18 » 30 »	0	-200	0	-200	+200	-200	+ 100	-100	+ 100	-100
» 30 » 50 »	0	-240	0	-240	+200	-200	+ 100	-100	+ 100	-100
» 50 » 80 »	0	-300	0	-300	+200	-200	+ 100	-100	+ 100	-100
» 80 » 120 »	0	-400	0	-400	+200	-200	+ 100	-100	+ 100	-100
» 120 » 180 »	0	-500	0	-500	+350	-250	+ 150	-150	+200	-100
» 180 » 250 »	0	-600	0	-600	+350	-250	+ 150	-150	+200	-100
» 250 » 315 »	0	-700	0	-700	+350	-250	+ 150	-150	+200	-100

6.3.8

2 (. 29—31)

29 —

2

d,	^A C/mp' ^A S		^A cfep	.	*ia	S _d	S _{ia}
	.	.					
10 .	0	-4	2,5	1,5	2	1,5	2
10 18 »	0	-4	2,5	1,5	2	1,5	2
» 18 » 30 »	0	-4	2,5	1,5	2,5	1,5	2,5
» 30 » 50 »	0	-5	3	2	2,5	2	2,5
» 50 » 80 »	0	-5	4	2	3	2	3
» 80 » 120 »	0	-6	5	2,5	3	2,5	3
» 120 » 180 »	0	-7	7	3,5	4	3,5	4
» 180 » 250 »	0	-8	7	4	5	5	5
» 250 » 315 »	0	-8	8	5	6	5,5	6

30 —

2

D,	^Dmp' ^Ds		^Dsp	^Dmp	*	^D1	S ^)	^ 1
	.	.						
18 .	0	-5	4	2,5	2,5	1,5	2,5	4
. 18 » 30 »	0	-5	4	2,5	2,5	1,5	2,5	4
» 30 » 50 »	0	-5	4	2,5	2,5	2	2,5	4
» 50 » 80 »	0	-6	4	2,5	4	2,5	4	6
» 80 » 120 »	0	-6	5	3	5	3	5	7
» 120 » 150 »	0	-7	5	3,5	5	3,5	5	7
» 150 » 180 »	0	-7	7	4	5	4	5	7
» 180 » 250 »	0	-8	8	5	7	5	7	10
» 250 » 315 »	0	-9	8	5	7	6	7	10
» 315 » 400 »	0	-10	10	6	8	7	8	11

1)

1

D₁

33.

31 —
2

d,	ABs		Λ^0		7s		AT1s		A72s	
10	0	-200	0	-200	+200	-200	+100	-100	+100	-100
10 18 »	0	-200	0	-200	+200	-200	+100	-100	+100	-100
» 18 » 30 »	0	-200	0	-200	+200	-200	+100	-100	+100	-100
» 30 » 50 »	0	-240	0	-240	+200	-200	+100	-100	+100	-100
» 50 » 80 »	0	-300	0	-300	+200	-200	+100	-100	+100	-100
» 80 » 120 »	0	-400	0	-400	+200	-200	+100	-100	+100	-100
» 120 » 180 »	0	-500	0	-500	+200	-250	+100	-100	+100	-150
» 180 » 250 »	0	-600	0	-600	+200	-300	+100	-150	+100	-150
» 250 » 315 »	0	-700	0	-700	+200	-300	+100	-150	+100	-150

6.3.9

(. . 32)

32 —

d,	7s				

18 30 .	+375	-375	—	—	—
. 30 » 50 »	+375	-375	—	—	—
» 50 » 80 »	+375	-375	—	—	—
» 80 » 120 »	+750	-750	+ 1000	-1000	-1000
» 120 » 180 »	+750	-750	+ 1000	-1000	-1000
» 180 » 250 »	+ 1000	-1000	+ 1500	-1500	-1500
» 250 » 315 »	+ 1000	-1000	+ 1500	-1500	-1500
» 315 » 400 »	+ 1000	-1000	+ 1500	-1500	-1500
» 400 » 500 »	+ 1000	-1000	+ 1500	-1500	-1500
» 500 » 630 »	+ 1500	-1500	+2000	-2000	-2000
» 630 » 800 »	+ 1500	-1500	+2000	-2000	-2000
» 800 » 1000 »	+2000	-2000	—	—	—

6.4

33.

33 —

	AD1s				

6 .	0	-36	+220	-36	-36
6 10 »	0	-36	+220	-36	-36
» 10 » 18 »	0	-43	+270	-43	-43
» 18 » 30 »	0	-52	+330	-52	-52
» 30 » 50 »	0	-62	+390	-62	-62
» 50 » 80 »	0	-74	+460	-74	-74
» 80 » 120 »	0	-87	+540	-87	-87
» 120 » 180 »	0	-100	+630	-100	-100
» 180 » 250 »	0	-115	+720	-115	-115
» 250 » 315 »	0	-130	+810	-130	-130
» 315 » 400 »	0	-140	+890	-140	-140
» 400 » 500 »	0	-155	+970	-155	-155
» 500 » 630 »	0	-175	+1100	-175	-175
» 630 » 800 »	0	-200	+1250	-200	-200
» 800 » 1000 »	0	-230	+1400	-230	-230
» 1000 » 1250 »	0	-260	+1650	-260	-260
» 1250 » 1600 »	0	-310	+1950	-310	-310
» 1600 » 2000 »	0	-370	+2300	-370	-370
» 2000 » 2500 »	0	-440	+2800	-440	-440

6.5


6.5.1

4.
5.


$$\begin{aligned} 1:12 & \quad () \\ & = 2^\circ 23' 9,4'' = 2,38594^\circ = 0,041643 \end{aligned}$$

$$\begin{aligned} d_1 &= d + \frac{\Delta}{30} \quad (1) \\ 1:30 & \quad () \\ & = 57'17,4'' = 0,95484^\circ = 0,016665 \end{aligned}$$

$$d_1 = d + \frac{\Delta}{30} \quad (2)$$



4 —



5 —

 $A_{dmp},$ $A_{d1mp} - A_{dmp},$ $V_{dsp},$

6.5.2

 $A_{dmp}, A_{d1mp} - A_{dmp}, V_{dsp}$
 $A_{d1mp} - A_{dmp}$

34—39.

34 —

1:12,

$d,$	V		$\wedge / 1 \quad " \quad V$		$\chi_{ctep}^{(1), (2)}$
	V	$"$	\wedge	V	
10	+22	0	+ 15	0	9
» 10 » 18 »	+27	0	+ 18	0	11
» 18 » 30 »	+33	0	+21	0	13
» 30 » 50 »	+39	0	+25	0	16
» 50 » 80 »	+46	0	+30	0	19
» 80 » 120 »	+54	0	+35	0	22

34

d,	V		V1 " V		\ D.2)
	
120 180 .	+63	0	+40	0	40
» 180 » 250 »	+72	0	+46	0	46
» 250 » 315 »	+81	0	+52	0	52
» 315 » 400 »	+89	0	+57	0	57
» 400 » 500 »	+97	0	+63	0	63
» 500 » 630 »	+110	0	+70	0	70
» 630 » 800 »	+125	0	+80	0	—
» 8 » 1000 »	+140	0	+90	0	—
» 1000 » 1250 »	+165	0	+105	0	—
» 1250 » 1600 »	+195	0	+125	0	—

^

2)

0 8.

35 —

,

1:12,

6

d,	V		V1 V		2)'
	
10 .	+15	0	+9	0	9
10 » 18 »	+18	0	+11	0	11
» 18 » 30 »	+21	0	+13	0	13
» 30 » 50 »	+25	0	+16	0	16
» 50 » 80 »	+30	0	+19	0	19
» 80 » 120 »	+35	0	+22	0	25
» 120 » 180 »	+40	0	+25	0	31
» 180 » 250 »	+46	0	+29	0	38
» 250 » 315 »	+52	0	+32	0	44
» 315 » 400 »	+57	0	+36	0	50
» 400 » 500 »	+63	0	+40	0	56
» 500 » 630 »	+70	0	+43	0	—

1)

2)

0 8.

36 —

,

1:12,

5

d,	V		V1 V		2)'
	
10 .	+9	0	+6	0	9
10 » 18 »	+11	0	+8	0	11
» 18 » 30 »	+13	0	+9	0	13
» 30 » 50 »	+16	0	+11	0	16

d,	V		V1 V		2)'
	
. 50 80 .	+ 19	0	+13	0	19
» 80 » 120 »	+22	0	+15	0	22
» 120 » 180 »	+25	0	+18	0	25
» 180 » 250 »	+29	0	+20	0	29
» 250 » 315 »	+32	0	+23	0	32
» 315 » 400 »	+36	0	+25	0	36
» 400 » 500 »	+40	0	+27	0	—

^A

2)

0 8.

37 —

, 1:12,

4

d,	V		V1 V		W"2)
	
18 30 .	+9	0	+4	0	4
. 30 » 50 »	+11	0	+6	0	6
» 50 » 80 »	+13	0	+6	0	6
» 80 » 120 »	+15	0	+8	0	8
» 120 » 180 »	+18	0	+8	0	8
» 180 » 250 »	+20	0	+10	0	10
» 250 » 315 »	+32	0	+12	0	12
» 315 » 400 »	+36	0	+12	0	12
» 400 » 500 »	+40	0	+14	0	—

^A

2)

0 8.

38 —

, 1:12,

2

d,	V		V1 V		2)'
	
18 30 .	+6	0	+2	0	2
. 30 » 50 »	+7	0	+3	0	3
» 50 » 80 »	+8	0	+3	0	3
» 80 » 120 »	+10	0	+4	0	4
» 120 » 180 »	+12	0	+4	0	4
» 180 » 250 »	+14	0	+5	0	5

^A

2)

0 8.

39—

1:30,

d,	V		V1 $\rightarrow \wedge$		'/dsp ¹⁺²⁾ .
50	+15	0	+30	0	19
50 » 80 »	+15	0	+30	0	19
» 80 » 120 »	+20	0	+35	0	22
» 120 » 180 »	+25	0	+40	0	40
» 180 » 250 »	+30	0	+46	0	46
» 250 » 315 »	+35	0	+52	0	52
» 315 » 400 »	+40	0	+57	0	57
» 400 » 500 »	+45	0	+63	0	63
» 500 » 630 »	+50	0	+70	0	70

¹
2)

0 8.

6.6**6.6.1**

6.6

190

360

6.6.2

(. 40 41)

40—

d, d ₂ ,	V /2		^cfep' ^c2sp	Si	7s		^T1s	
18	0	-8	6	10	+20	-250	+150	-400
18 » 30 »	0	-10	8	10	+20	-250	+150	-400
» 30 » 50 »	0	-12	9	10	+20	-250	+150	-400
» 50 » 80 »	0	-15	11	10	+20	-300	+150	-500
» 80 » 120 »	0	-20	15	15	+25	-300	+200	-500
» 120 » 180 »	0	-25	19	15	+25	-400	+200	-600
» 180 » 250 »	0	-30	23	20	+30	-400	+250	-600
» 250 » 315 »	0	-35	26	25	+40	-400	—	—
» 315 » 400 »	0	-40	30	30	+40	-500	—	—
» 400 » 500 »	0	-45	34	30	+50	-500	—	—
» 500 » 630 »	0	-50	38	35	+60	-600	—	—
» 630 » 800 »	0	-75	55	40	+70	-750	—	—
» 800 » 1000 »	0	-100	75	45	+80	-1000	—	—
» 1000 » 1250 »	0	-125	95	50	+100	-1400	—	—
» 1250 » 1600 »	0	-160	120	60	+120	-1600	—	—
» 1600 » 2000 »	0	-200	150	75	+140	-1900	—	—
» 2000 » 2500 »	0	-250	190	90	+160	-2300	—	—

d₂ 190

D,	^Dmp		^Dsp	S _e
	.	.		
10 18 .	0	-11	8	
. 18 » 30 »	0	-13	10	
» 30 » 50 »	0	-16	12	
» 50 » 80 »	0	-19	14	
» 80 » 120 »	0	-22	17	
» 120 » 180 »	0	-25	19	
» 180 » 250 »	0	-30	23	
» 250 » 315 »	0	-35	26	
» 315 » 400 »	0	-40	30	si
» 400 » 500 »	0	-45	34	
» 500 » 630 »	0	-50	38	
» 630 » 800 »	0	-75	55	
» 800 » 1000 »	0	-100	75	
» 1000 » 1250 »	0	-125	95	
» 1250 » 1600 »	0	-160	120	
» 1600 » 2000 »	0	-200	150	
» 2000 » 2500 »	0	-250	190	
» 2500 » 2850 »	0	-300	225	

D 360

6.6.3

6 (. 42 43)

d, d ₂ ,	V		^cfep' ^c/2sp	Si	7s		^T1s	

18 .	0	-8	6	5	+20	-250	+ 150	-400
. 18 » 30 »	0	-10	8	5	+20	-250	+ 150	-400
» 30 » 50 »	0	-12	9	6	+20	-250	+ 150	-400
» 50 » 80 »	0	-15	11	7	+20	-300	+ 150	-500
» 80 » 120 »	0	-20	15	8	+25	-300	+200	-500
» 120 » 180 »	0	-25	19	9	+25	-400	+200	-600
» 180 » 250 »	0	-30	23	10	+30	-400	+250	-600
» 250 » 315 »	0	-35	26	13	+40	-400	—	—
» 315 » 400 »	0	-40	30	15	+40	-500	—	—
» 400 » 500 »	0	-45	34	18	+50	-500	—	—
» 500 » 630 »	0	-50	38	21	+60	-600	—	—
» 630 » 800 »	0	-75	55	25	+70	-750	—	—
» 800 » 1000 »	0	-100	75	30	+80	-1000	—	—
» 1000 » 1250 »	0	-125	95	35	+100	-1400	—	—
» 1250 » 1600 »	0	-160	120	40	+120	-1600	—	—
» 1600 » 2000 »	0	-200	150	45	+140	-1900	—	—
» 2000 » 2500 »	0	-250	190	50	+160	-2300	—	—

d₂ 190

D, .	ΔDmp		vDsp	S _e
	.	.		
10 18 .	0	-11	8	
. 18 » 30 »	0	-13	10	
» 30 » 50 »	0	-16	12	
» 50 » 80 »	0	-19	14	
» 80 » 120 »	0	-22	17	
» 120 » 180 »	0	-25	19	
» 180 » 250 »	0	-30	23	
» 250 » 315 »	0	-35	26	
» 315 » 400 »	0	-40	30	
» 400 » 500 »	0	-45	34	
» 500 » 630 »	0	-50	38	
» 630 » 800 »	0	-75	55	
» 800 » 1000 »	0	-100	75	
» 1000 » 1250 »	0	-125	95	
» 1250 » 1600 »	0	-160	120	
» 1600 » 2000 »	0	-200	150	
» 2000 » 2500 »	0	-250	190	
» 2500 » 2850 »	0	-300	225	

D 360

6.6.4

5 (. 44 45)

d, d ₂ , .	V ' /2		^cfep' ^c/2sp	Si	^7s		^T1s	

18 .	0	-8	6	3	+20	-250	+ 150	-400
. 18 » 30 »	0	-10	8	3	+20	-250	+ 150	-400
» 30 » 50 »	0	-12	9	3	+20	-250	+ 150	-400
» 50 » 80 »	0	-15	11	4	+20	-300	+ 150	-500
» 80 » 120 »	0	-20	15	4	+25	-300	+200	-500
» 120 » 180 »	0	-25	19	5	+25	-400	+200	-600
» 180 » 250 »	0	-30	23	5	+30	-400	+250	-600
» 250 » 315 »	0	-35	26	7	+40	-400	—	—
» 315 » 400 »	0	-40	30	7	+40	-500	—	—
» 400 » 500 »	0	-45	34	9	+50	-500	—	—
» 500 » 630 »	0	-50	38	11	+60	-600	—	—
» 630 » 800 »	0	-75	55	13	+70	-750	—	—
» 800 » 1000 »	0	-100	75	15	+80	-1000	—	—
» 1000 » 1250 »	0	-125	95	18	+ 100	-1400	—	—
» 1250 » 1600 »	0	-160	120	25	+ 120	-1600	—	—
» 1600 » 2000 »	0	-200	150	30	+ 140	-1900	—	—
» 2000 » 2500 »	0	-250	190	40	+ 160	-2300	—	—

d₂ 190

D, .	^A Dmp		^v Dsp	^s e
	.	.		
10 18 .	0	-11	8	
. 18 » 30 »	0	-13	10	
» 30 » 50 »	0	-16	12	
» 50 » 80 »	0	-19	14	
» 80 » 120 »	0	-22	17	
» 120 » 180 »	0	-25	19	
» 180 » 250 »	0	-30	23	
» 250 » 315 »	0	-35	26	
» 315 » 400 »	0	-40	30	si
» 400 » 500 »	0	-45	34	
» 500 » 630 »	0	-50	38	
» 630 » 800 »	0	-75	55	
» 800 » 1000 »	0	-100	75	
» 1000 » 1250 »	0	-125	95	
» 1250 » 1600 »	0	-160	120	
» 1600 » 2000 »	0	-200	150	
» 2000 » 2500 »	0	-250	190	
» 2500 » 2850 »	0	-300	225	

D 360

6.6.5

4 (. 46 47)

d, d ₂ , .	V /2		^A c _{fep} '	^A c/2sp	Si	7s		^A T1s	

18 .	0	-7	5	2	+20	-250	+ 150	-400	
. 18 » 30 »	0	-8	6	2	+20	-250	+ 150	-400	
» 30 » 50 »	0	-10	8	2	+20	-250	+ 150	-400	
» 50 » 80 »	0	-12	9	3	+20	-300	+ 150	-500	
» 80 » 120 »	0	-15	11	3	+25	-300	+200	-500	
» 120 » 180 »	0	-18	14	4	+25	-400	+200	-600	
» 180 » 250 »	0	-22	17	4	+30	-400	+250	-600	
» 250 » 315 »	0	-25	19	5	+40	-400	—	—	
» 315 » 400 »	0	-30	23	5	+40	-500	—	—	
» 400 » 500 »	0	-35	26	6	+50	-500	—	—	
» 500 » 630 »	0	-40	30	7	+60	-600	—	—	
» 630 » 800 »	0	-50	40	8	+70	-750	—	—	

d₂ 190

47 —

4

D,			v_{Dsp}	s_e
	.	.		
10 18 .	0	-7	5	
. 18 » 30 »	0	-8	6	
» 30 » 50 »	0	-9	7	
» 50 » 80 »	0	-11	8	
» 80 » 120 »	0	-13	10	
» 120 » 180 »	0	-15	11	
» 180 » 250 »	0	-20	15	Si
» 250 » 315 »	0	-25	19	
» 315 » 400 »	0	-28	21	
» 400 » 500 »	0	-33	25	
» 500 » 630 »	0	-38	29	
» 630 » 800 »	0	-45	34	
» 800 » 1000 »	0	-60	45	

D 360

6.6.6

2 (. 48 49)

48 —

2

d, d_2	W ⁴ /2		$\wedge c f e p' \wedge c/2sp$	ST
	.	.		
18	0	-7	5	1
» 18 » 30 »	0	-8	6	1,2
» 30 » 50 »	0	-10	8	1,5
» 50 » 80 »	0	-12	9	2
» 80 » 120 »	0	-15	11	2
» 120 » 180 »	0	-18	14	3
» 180 » 250 »	0	-22	17	3
» 250 » 315 »	0	-25	19	4
» 315 » 400 »	0	-30	23	4
» 400 » 500 »	0	-35	26	-
» 500 » 630 »	0	-40	30	—
» 630 » 800 »	0	-50	—	—

1)

S|

(

d

)

s|

D,			ΔDsp	S _e
	.	.		
10 18 .	0	-7	5	
. 18 » 30 »	0	-8	6	
» 30 » 50 »	0	-9	7	
» 50 » 80 »	0	-11	8	
» 80 » 120 »	0	-13	10	
» 120 » 180 »	0	-15	11	s _j
» 180 » 250 »	0	-20	17	
» 250 » 315 »	0	-25	19	
» 315 » 400 »	0	-28	21	
» 400 » 500 »	0	-33	25	
» 500 » 630 »	0	-38	29	
» 630 » 800 »	0	-45	34	

7

7.1

7.2

,

6.

7.3

, , ,

7.4

3 HRC.

, 1, ..., 5

50.

50

	120 ° , HRC	
	35 55	35 55
4 ¹⁾	60 ... 63	
15, 15-, 15-, 15-	61 ... 65	
15 , 15 - , 15 - , 15 -	60 ... 64	58 ... 62
20		
18 ²⁾	61 ... 65	
20 2 4 ²⁾	58 ... 63	
15 1 ²⁾	57 ... 61	

¹⁾

32 ... 44 HRC.

²⁾

7.5

 Ra ,

2789,

,

51.

51

		$d \quad D$			
		80	80 250	250 500	500 2500
-	0, 6 , 6, 5 4, , 2	1.25	1.25	2.5	2.5
		0.63	1.25	1.25	2.5
		0.32	0.63	0.63	
	0, 6 , 6, 5 4, , 2	0.63	1.25	1.25	2.5
		0.32	0.63	0.63	1.25
		0.32	0.63	0.63	
	0, 6 , 6, 5 4, , 21)	2.5	2.5	2.5	2.5
		1.25	1.25	2.5	2.5
		0.63	0.63	1.25	
1) 0,32 0,63		2		Ra 80 80	.

 Ra

7.6

 K_{ia} K_t

4, 2;

3

180

5

 $S|, S_e$ S_{ia}, S_{ea} S_{e1} S_{ea1}

4, 2;

10

180

5

5;

5.

10

 $, S|, S_e, S_{e1},$ $, S_{ia}, S_{ea}, S_{ea1}$

10

15 %

1—8, 11, 12, 23, 24, 26, 27.

 $S|, S_e, S_{e1}$

5—12.

 $S_{ia}, S_{ea}, S_{ea1},$

7.7

6-

7.8

—

24810.

7.9	,	,				
,	-	6000,	,			
		6, 5, 4,	2.	,		
,	,	,	,	,		
7.10	,	,	,	,		
	18854.		,			
	,	,	,	,		
	18854.		,			
7.11	,	18855.	,			
,	,	18855,				
7.12	,	,	,			
—	,	,	,			
7.13	,	,	,			
7.14	,	,	,			
7.15	,				7242	
9592,					8882,	
7.16		3478.				
7.17						
2893.						
7.18				3722,	—	6870,
			—	22696,		
—	25255,		(,) —	,
7.19			,	,		
			,	,		
7.20			,			5
7.21			,			
7.22	,	,	,	,)
7.23			,			

7.25 ,

8

8.1

3 130

52.

52 —

	,
1	15 .
2	. 15 » 30 »
3	» 30 » 60 »
4	» 60 » 100 »
5	» 100 » 130 »

8.3.1

(

933

833

834

8.4							
8.5							
8.6	8						
8.7					18242 ¹⁾		
8.8				²⁾ (
)						
				$AQL = 2,5 \%$			$AQL = 7,5 \%$,
					18242.		

8.9 , , 9 150 . —
150 . — 18242
8.10 , , . S-2 18242.
8.11 , , Re — 18242
8.12 , , 18321.
8.13 —
24297

9

9.1

8.050

9.2

9.3

9.4

1)

2)

2859-1—2007 «

1.

»

«

9.5

9.6

9.7

9.8

1).

9.9

9.10

9.11

9.12

53.

53

		1), ,	2), ,
<i>d</i>	10 .	1,5	0,8
	.10	1,5	2,5
<i>D</i>		1,5	2,5

11

2)

9.13

54 55.

54 —

55 —

30°

,	,
30	5
.30 .50 »	10
» 50 » 80 »	20
» 80 » 120 »	35
» 120 » 180 »	70
» 180	140

,	,
30	40
.30 .50 »	80
» 50 » 80 »	120
» 80 » 120 »	150
» 120	150

11

1.

52545.1—2006 «

».

9.14

56.

56 —

$r_s \min$	
0,6 0,6	$r_s \max + 0,5$ $r_s \max$

9.15



 d_{sp} d_s ,6 7.
(), $d_{sp} \min$ $d_{sp} \max$,

Рисунок 6





Рисунок 7

 $d_{s\max}$ $d_{s\min}$ $d_{sp\ min}$ $d_{sp\ max}$

:

 d_{mp} : A_{dmp} : V_{dsp} : V_{dmp} : A_{ds} : V_{ds} : d_m : A_{dm} :

10

, $A_{d1mp} - A_{dmp}$,

()





Рисунок 8






Рисунок 14




Рисунок 15




Рисунок 16




Рисунок 17

9.20 , 18, 19.

$$T_s (\mathsf{T}_{1s})$$

T_s (T_{1s})

A_{rs} (A_{ris})




Рисунок 18

T_s (T_{1s})





Рисунок 19

9.21

T_{1s}

20.



20

T_{1s}

9.22

T_{2s}

21.

(

)

() .




Рисунок 21


72s

9.23

S_d

1.

22.



22

 s_d

2.



23.

 s_d

(3)


 s_{dr}

1



23

49




24

9.24

S_D

24.



9.25

S_{D1}

25.

90°

S_{D1}

25

9.26

(

)

K_{ia}

26—29.




Рисунок 26




Рисунок 27




Рисунок 28




Рисунок 29

9.27


 K_{ia} 27, 30, 31,
30, 31.

Рисунок 30




Рисунок 31

K_{ia}

9.28
 ()
 26 (), 32, 33.




Рисунок 32




Рисунок 33

9.29
 — ,
 27, 30, 31,
 30, 31.

27,

9.30 S_{ia}

34, 35.





Рисунок 34



35

36.




Рисунок 36

1,67.

9.31

 S_{ea}

37.





Рисунок 37

 S_{ea}


9.32

 S_{ea1}

38, 39.



38



39

S_{ea1}

9.33

40, 41.




Рисунок 40




Рисунок 41

9.34

Kj

42, 43.




Рисунок 42





Рисунок 43

()

9.35



44.

Рисунок 44

9.36


S|

S_e

47 —

45 —

46 —



45




Рисунок 46




Рисунок 47

9.37

S|


S_e

48, 49.


S|

S_e

50, 51.



48



49




Рисунок 50




Рисунок 51

9.38

,

57.


,

57 —

					100
	, 0,6	6	5	4	± 1
3 .3 » 30 » » 30 » 50 »	2 2	1,5 1,3	1 0,7	0,7 0,5	8 8
» 50 » 80 » » 80	3 4	2 $\wedge 5$	1,5 L5	1 1	10 13 15

9.39

() 53 ()



52


 G_r

0,

0,5 %

18854.

58.



53

57

120° ().
 G_r

58 —

d ,	¹⁾ ,	
30	25	50
» 30 » 50 »	30	60
» 50 » 80 »	35	70
» 80 » 120 »	40	80
» 120 » 200 »	50	100

¹⁾ 0,005 ,
18854.

10

10.1
3189,

3189,

10.2 , ,
«0».
«0»,
«X».
«0» ,

«N», 6

1 80-92518.
2 30-3628.

30 36-3628.

, , , ,
3189.
10.3 , , ,
BELARUS, KAZAKHSTAN, RUSSIA, UKRAINE,
UZBEKISTAN.

, 3189, , -

3189 -

10.4 ,

2 :

, ,
() ,

10.5 ,

10 , ,

10
4 2
10

10.6 ,

25 34

: 25-34;

1 7510
97510 7510

67510.

2 7510.

32210, 42210, 52210
32210.

10.7 ,

10.8 ,

11 ,
11.1 ,

11.2 , ,
, 60 % , , ,
(20 ± 5) ° ,

11.3 300 8 5, 4, 2
30
6, 5, 4, 2

11.4 , , ,
2991, 9142, 16148, 24634.
8 , 300 515
10354, 16272

11.5 , , ,
11.6 , ()
, ().

11.7 , , ,
11.8 (())
11.9 , (), ;
; ();
();

7.19.
— 7.19

11.10 14192.

7.19;
 ;
 14192: « »; « ».
 0,5
 15
 —
 7.19

11.11
 (, , ,).

12

12.1

12.2

12.3

5377 20531.

12.4

3325.
 20531.
 4657,

13

13.1

13.2

)

13.3

, —24
 ,

).

()

.1

.1.1

 $d_s \quad d_{sp}$


)

(

.1,

.1).

(



.1 —

.1 —

1	$\wedge s11, \wedge s12, \wedge s13, \dots, d_{s1y}, \dots, d_{s1n}$
2	$\wedge s21, d_{s22} < d_{s23}, \dots, d_{s2y}, \dots, d_{s2n}$
3	$d_{s3} \wedge d_{s32}, d_{s33}, \dots, d_{s3j}, \dots, d_{s3n}$
/	$\wedge s/1, d_{si2}, d_{si3} < \dots, d_{sij}, \dots, d_{sin}$
	$d_{sm1}, d_{sm2}, d_{sm3} < \dots, d_{smj}, \dots, d_{smn}$
— d_{sy}	j
	/.

.1.2

 d_m

,

(.1).

$$d_m = [\max(d_{s11}, d_{s12}, d_{s13}, \dots, d_{s1y}, \dots, d_{smn}) + \min(d_{s11}, d_{s12}, d_{s13}, \dots, d_{s1y}, \dots, d_{smn})]/2. \quad (A.1)$$

 d_m .— ($\wedge, 2, 3, \dots, \wedge$)

2, 3, — , .

min ($\wedge, 2, 3, \dots, \wedge$) $a_v, 2, 3, \dots, \wedge$

.1.3

 d_{mp}

.2.

.2 —

	\wedge	
1	d_{mp}/i	$[\max(d_{s11} \dots d_{s1n}) + \min(d_{s11} \dots d_{s1n})]/2$
2	d_{mp2}	$[\max(d_{s21} \dots d_{s2n}) + \min(d_{s21} \dots d_{s2n})]/2$
3	d_{mp3}	$[\max(d_{s31} \dots d_{s3n}) + \min(d_{s31} \dots d_{s3n})]/2$
/	d_{mpi}	$[\max(d_{s1} \dots d_{sjn}) + \min(d_{s1} \dots d_{sjn})]/2$
	d_{mpm}	$[\max(d_{sm1} \dots d_{smn}) + \min(d_{sm1} \dots d_{smn})]/2$

.1.4

 V_{dmp}

(.2)

$$V_{dm} = \max(\wedge_{mp1}, d_{mp2}, \dots, \wedge_{mpm}) - \min(\wedge_{mp1}, d_{mp2}, \dots, \wedge_{mpm}) \quad (.2)$$

.1.5

 V_{dsp}

«

»

(. . .).

	$\wedge_{c/sp}$	
1	\wedge_{dsp1}	$[\max(d_{s11} \dots d_{s1n}) - \min(d_{s11} \dots d_{s1n})]$
2	\wedge_{dsp2}	$[\max(d_{s21} \dots d_{s2n}) - \min(d_{s21} \dots d_{s2n})]$
3	\wedge_{dsp3}	$[\max(d_{s31} \dots d_{s3n}) - \min(d_{s31} \dots d_{s3n})]$
/	\wedge_{dspi}	$[\max(d_{s1} \dots d_{sjn}) - \min(d_{s1} \dots d_{sjn})]$
m	\wedge_{dspm}	$[\max(d_{sm1} \dots d_{smn}) - \min(d_{sm1} \dots d_{smn})]$

.1.6

 V_{ds}

$\vee, \wedge, (\dots), (\dots), (\dots).$

$$V_d s = \max(d_{s1}, d_{s2}, \dots, d_{s13}, \dots, d_{smf}) - \min(d_{s11}, d_{s12}, d_{s13}, \dots, d_{sm1}, \dots, d_{smn}) \quad (. .)$$

.2

.1.

$$\begin{aligned}
 & D_s \quad D_{sp}; \\
 & D_m; \quad D_{mp}; \\
 & V_{Ds}, \quad V_{Dsp}; \\
 & V_{Dmp}.
 \end{aligned}$$

()

.1

.1— . .

.1—

	492 [2]	620 [3]	AFBMA, 20 [4]	JISB 1514 [5]
		0	-1 RBEC-1	0
6	6	6	-3 RBEC-3	6
5	5	5	-5 RBEC-5	5
4	4	4	-7	4
	-	-	-	-
2	2	2	-9	2

.2—

	492 [2]	620 [3]	AFBMA 19.1 [6]	JISB 1514 [5]
0	-	-	-	-
		0		0
6	6	6	N	6
6	-	-	-	6
5	5	5		5
4	4	4		4
2	2	-		-

. — . —

	199 [7]	620 [3]
		0
6	6	6
5	5	5
4	4	4
2	-	-

- [1] 492:2002 (ISO 492:2002 «Rolling bearings — Radial bearings — Tolerances»)
- [2] 620—1988 2. (DIN 620—1988 Teil 2 Walzager; Toleranzen Radiallager)
- [3] AFBM 20—1987 (AFBMA Standard 20—1987, Radial Bearings of Ball, Cylindrical roller and spherical)
- [4] JISB 1514 (JIS 1514, Tolerances for rolling bearings)
- [5] AFBMA 19.1—1987 (AFBMA Standard 19.1—1987, Tapered roller bearings. Metric design)
- [6] 199—2005 (ISO 199:2005 «Rolling bearings — Thrust ball bearings — Tolerances»)

621.822.6:006.354 21.100.20 16 46 000

16.02.2012. 27.03.2012. 60 »84^{1/8}.
 7,90. 7,25. 416 272.

« » , 123995 , . 4.
www.gostinfo.ru info@gostinfo.ru
« » .
« » — . « » , 105062 , . 6.